

State of Wisconsin - Department of Natural Resources  
Substance Release Notification Report (SERTS)  
Report created on 04/25/2011

SPILL ID# 20110324NE59-1 BRRTS# 04-59-556975

|   |   |                           |                                      |
|---|---|---------------------------|--------------------------------------|
| Incident Date & Time:<br>03/24/2011 13:30   | Reported Date & Time:<br>03/24/2011 13:57 | BRRTS No:<br>04-59-556975 | Spill ID:<br>20110324NE59-1          |
| DATCP Reported? No<br>DATCP Transferred? No | NFA Letter Sent?<br>No                    | ERP Transferred?<br>No    | Incident Closed?<br>Yes : 04/22/2011 |

| Location   |   |   |  |
|--|---|---|--|
| Region:<br>NE  | County:<br>Shawano                          | Municipality:<br>SHAWANO, CITY OF                   |  |
| Facility/Property Name and Street Address:<br>AARROWCAST INC<br>2900 E RICHMOND ST |   | Description:<br>SOUTH LOADING DOCK AREA - GRAVEL    |  |
| Facility Type: Industrial Facility (Foundry/Factory/Plating/Manufacturing) 632350  |   |   |  |
| Lat/Long:<br>44° 46' 307" , 88° 34' 768"   | PLSS:<br>Move to get away<br>From 55709 Geo | WTM:<br>X 632363 Y 478579<br>add to SDE-MGS-7/12/11 |  |
| Weather Conditions: Sunny  |   |   |  |

| Responsible Parties  |   |   |  |
|--|---|---|--|
| Name/Address (1):<br>SADOFF & RUDOY INDUSTRIES<br>240 W ARNDT ST<br>FOND DU LAC, WI 54936-1138<br>(920) 906-5619 x Primary | Contact:<br>DAVID BORSUK<br>SADOFF IM MANAGER<br>(920) 906-5620 x primary | Other Contact:<br>MIKE MATHEY<br>AARROWCAST FACILITY<br>MANAGER<br>(715) 851-4942 x primary | Spill Packet:<br>Sent on 03/25/2011<br>to<br>BORSUKD@SADOFF.COM<br>via email |

| Cause  |
|--|
| DRIVER RICHARD RHOADES FROM SADOFF WAS DUMPING SCRAP METAL AT THE AARROWCAST COMPANY IN SHAWANO. AFTER DUMPING THE SCRAP METAL THE DRIVER OBSERVED THE OIL FILTER FROM THE HYDRAULIC LINE COME OFF THE LINE AND THE HYDRAULIC FLUID (70 GALLONS) SPILLED OUT. DRIVER STATES THE SAME INCIDENT OCCURRED THE PRIOR EVENING AT 5:30PM. DRIVER STATES HE DROVE THE TRUCK BACK TO SADOFF AND THEY FIXED THE ISSUE, HOWEVER THE SAME INCIDENT OCCURRED AGAIN THIS AFTERNOON. |
| Cause Type: Hydraulic Line Break   |

| Substances    |                  |              |               |        |       |      |
|---------------|------------------|--------------|---------------|--------|-------|------|
| Name          | Other / Comments | Amt Released | Amt Recovered | Type   | Color | Odor |
| Hydraulic Oil |                  | 70.0 Gal     | 70.0 Gal      | LIQUID |       |      |

| Environmental Impacts / Damages |                         |                 |                   |
|---------------------------------|-------------------------|-----------------|-------------------|
| Environmental Impacts:<br>SOIL  | Resource Damages:<br>No | Injuries:<br>No | Evacuation:<br>No |

| Cleanup Actions                    |   |
|------------------------------------|---|
| Method                             | Description   |
| Absorbent (oil dry, sand, sawdust) | PLACED IN AREAS WHERE WATER/HYDRAULIC FLUID HAD POOLED    |
| Dike Built                         | SAND BERMS PLACED ON EAST AND WEST SIDE TO CONTAIN RUNOFF |
| Excavation                         | SCRAPPED UP SNOW-ICE AND GRAVEL                           |
| Vacuum                             | VACUUMED UP THE OILY WATER                                |


| Cleanup Action Comments  |
|--|
| ARROWCAST PLACED SAND DAMS TO CONTAIN THE OILY RUNOFF WATER AND THE FIRE DEPT PLACED ABSORBENT PADS AND BOOM IN THE DRIVEWAY. VEOLIA WAS CALLED IN TO COMPLETE THE CLEANUP. VEOLIA USED A VACUUM TRUCK TO REMOVE THE OILY WATER AND THEY USED A SKID STEER TO SCRAPE UP THE CONTAMINATED SNOW-ICE AND GRAVEL. THE CONTAMINATED MATERIAL WAS CONTAINERIZED AND DISPOSED OF AT THE SAFETY KLEEN FACILITY IN KIMBERLY WI. |

| Contractors Hired |             |
|-------------------|-------------|
| Name              | Description |



**State of Wisconsin - Department of Natural Resources**  
**Substance Release Notification Report (SERTS)**  
**Report created on 04/25/2011**

SPILL ID# 20110324NE59-1 BRRTS# 04-59-556975

|  |   |  |                               |       |
|--|---|--|-------------------------------|-------|
| VEOLIA ENVIRONMENTAL SERVICES  |   |  |                               |       |
| <b>Waste Destinations</b>  |   |  |                               |       |
| Location   |   | Description  |                               |       |
| SAFETY KLEEN, KIMBERLY WI  |   | 1,000 GALLONS OF OILY WATER, 28 DRUMS OF OILY SNOW AND GRAVEL AND 4 DRUMS OF ABSORBENT PADS AND BOOM |                               |       |
| <b>Agencies Notified / On Scene</b>  |   |  |                               |       |
| Agency   |   | Notified   | On Scene                      |       |
| DNR  |   | X  | X                             |       |
| FIRE DEPARTMENT  |   | X  | X                             |       |
| LEPC OF LOCAL EMERG MGT  |   | X  | X                             |       |
| NATL RESP CTR  |   | X  |                               |       |
| SHAWANO HAZMAT   |   | X  | X                             |       |
| <b>Additional Comments</b>   |   |  |                               |       |
| <p>SUBMITTED VIA SERTS WEB FORM REF # 5649. NRC REPORT # 971051. WARDEN SCHRAUFNAGEL WAS CONTACTED TO RESPOND TO A SPILL AT AARROWCAST INC. IN SHAWANO OF A HYDRAULIC FLUID SPILL. SCHRAUFNAGEL RESPONDED AND MADE CONTACT WITH MIKE MATHEY-FACILITY MANAGER. SCHRAUFNAGEL GAVE MATHEY A COPY OF THE SPILLS PACKET. MATHEY WALKED SCHRAUFNAGEL TO A SCRAP METAL DOCKING AREA ON THE SOUTH END OF THE PLANT. SCHRAUFNAGEL OBSERVED A SEMI TRUCK PARKED IN THE LOADING DOCK. SCHRAUFNAGEL OBSERVED HYDRAULIC FLUID ON TOP OF SNOW AND HYDRAULIC FLUID ON TOP OF WATER SLOWLY FLOWING TO THE EAST DOWN THE GRAVEL DRIVEWAY. SCHRAUFNAGEL OBSERVED SHAWANO HAZMAT ON SITE AND THEY WERE PLACING DOWN ABSORBENT BOOMS AND ABSORBANT PADS. SCHRAUFNAGEL OBSERVED AARROWCAST PLACE A SAND BERM ON THE EAST SIDE OF THE GRAVEL DRIVEWAY AND THEY PLANNED TO PLACE A BERM ON THE WEST SIDE OF THE GRAVEL DRIVEWAY TO STOP OIL FROM FLOWING OFF THE SITE. SCHRAUFNAGEL SPOKE TO THE DRIVER OF THE SEMI-TRUCK IDENTIFIED AS RICHARD RHOADES OF SADOFF. RHOADES STATED THE OIL FILTER CAME OFF THE HYDRAULIC LINE AND THE OIL FROM THE RESERVOIR TANK SPILLED OUT (APROX 70 GAL). RHOADES STATED THAT THE SAME INCIDENT OCCURRED THE PREVIOUS NIGHT AT 5:30PM. RHOADES STATES HE TOOK THE TRUCK BACK TO SADOFF AND THEY FIXED THE TRUCK. RHOADES STATES HE TESTED THE HYDRAULICS THIS MORNING AND IT WORKED FINE. THE INCIDENT OCCURRED A SECOND TIME THIS AFTERNOON RESULTING IN ANOTHER 70 GAL OF HYDRAULIC OIL RELEASED ONTO THE GRAVEL DRIVEWAY. SCHRAUFNAGEL SPOKE WITH MATHEY WHO STATED THAT HE WAS HIRING VEOLIA TO CLEAN THE SITE. - SCHRAUFNAGEL</p> |   |  |                               |       |
| <b>Enforcement Action/Citation</b>   |   |  |                               |       |
| <p>04-20-2011, DNR RECEIVED A COPY OF VEOLIA'S SPILL CLEAN UP REPORT FROM SADOFF. THE SPILL WAS PROPERLY CLEANED UP, NO FURTHER CLEAN UP NEEDED.</p> <p>Enforcement Action/Citation? No</p>  |   |  |                               |       |
| Case Activity Reports:   |   |  |                               |       |
| <b>Person Reporting</b>  |   |  |                               |       |
| Name   | Representing / Address  | Primary Phone  | Secondary Phone               |       |
| MIKE MATHEY  | AARROWCAST INC  | (715) 851-4942 x   | (715) 526-3600 x 1228         |       |
| <b>Contractors Hired</b>   |   |  |                               |       |
| Name / Address   |   |  | Zone Contractor Hired by DNR? |       |
|  |   |  | No                            |       |
| <b>Contacts</b>  |   |  |                               |       |
| Role   | Name  | Office Phone   | Date                          | Time  |
| Prepared By:   | MARK SCHRAUFNAGEL   | (715) 853-8686 x   | 03/24/2011                    |       |
| Person Notified:   | MARK SCHRAUFANGEL   | (715) 853-8686 x   | 03/24/2011                    | 13:57 |
| Investigated By:   | MARK SCHRAUFNAGEL   | (715) 853-8686 x   | 03/24/2011                    | 14:15 |
| Incident Commander:  |   |  |                               |       |
| Spill Coordinator:   | JASON MOELLER, NE Region  | (920) 662-5492 x   | 04/22/2011                    |       |
| <b>Electronic Attachments (list)</b>   |   |  |                               |       |
| Name   |   | Type   |                               |       |



# SADOFF & RUDOY INDUSTRIES, LLP

Customer Confidence People Power Accountability

RECEIVED

APR 20 2011

WI DNR - GREEN BAY


April 19, 2011

**Alfred Muchin Co.**  
(920) 684-3388  
1600 S. 26<sup>th</sup> St.  
P.O. Box 323  
Manitowoc, WI 54220-0323

**Gus Holman Co.**  
(920) 457-2431  
3313 N. 21<sup>st</sup> St.  
P.O. Box 531  
Sheboygan, WI 53082-0531


**Sadoff Iron & Metal Co.**  
(920) 434-0137  
1901 Lineville Rd.  
Green Bay, WI 54313

**Sadoff Iron & Metal Co.**  
(920) 921-2070  
240 W. Arndt St.  
P.O. Box 1138  
Fond du Lac, WI 54936-1138



**Lawent Iron & Metal Co.**  
(920) 361-1450  
478 E. Huron St.  
P.O. Box 264  
Berlin, WI 54923

**Sadoff Iron & Metal Co.**  
(920) 651-9398  
36 E. 10<sup>th</sup> Ave.  
P.O. Box 1066  
Oshkosh, WI 54903-1066



**Sadoff Iron & Metal Co.**  
(402) 470-2510 – Ferrous  
5510 NW 39<sup>th</sup> St.  
P.O. Box 83465  
Lincoln, NE 68501-3465  
(402) 434-2890 – Nonferrous

Mr. Jason Moeller  
NER Spills Coordinator/Hydrologist  
Wisconsin Department of Natural Resources  
2984 Shawano Ave.  
Green Bay WI 54313

RE: Hydraulic Oil Release; Aarrowcast Foundry, March 24, 2011

Dear Mr. Moeller,

On March 24, 2011 approximately 35 gallons of hydraulic oil were released from a Sadoff & Rudoy Industries, LLP truck at the Aarrowcast Foundry, Shawano, Wisconsin. The release was due to a hydraulic pump failure. The Shawano Fire/Hazmat Department and Wisconsin Department of Natural Resources were contacted by Aarrowcast Foundry and Veolia Environmental Services Special Services was contacted to control the release and conduct the cleanup.

Veolia contained the release, cleaned up the site, and recycled the material at Safety Kleen – Kimberly. The Veolia narrative and documentation (VES-SS Project Number 4901570.11.039) is attached.

Sadoff requests closure of this incident. Please contact me if you need any additional information.

Sincerely,

David J. Borsuk  
Manager – Industrial Marketing and Quality Control

cc: Mark Katz – VP Operations  
Jeff Young – Fleet Manager  
Mike Dovichi

djb/kf1106

**Defining the  
Art of Quality  
and Service.**



**RECEIVED**

**APR 22 2011**

**WI DNR - GREEN BAY**

April 18, 2011

Wisconsin Department of Natural Resources  
Attn: Jason Moeller  
Northeast Region  
2984 Shawano Avenue  
Green Bay, WI 54313

Dear Mr. Moeller:

Enclosed, you will find the No Further Action (NFA) Report summarizing response activities to the spill reported to your office on 3/24/11. If you require any additional information on this matter, feel free to call me at (715) 526-3600, ext. 1228. If I do not hear from you, I will assume this matter has been closed with no further action on our part needed.

Sincerely,



Mike Mathey  
Facility Manager  
Aarrowcast, Inc.

Attachment: Veolia Report



## **INCIDENT RESPONSE REPORT**

Prepared for

**ARROWCAST INC.**

**VES-SS PROJECT NUMBER: 4901570.11.039**

**RESPONSE DATE: MARCH 24, 2011**

Prepared by  
Greg Potts  
Project Manager



## **TABLE OF CONTENTS**

---

- I. INCIDENT SUMMARY
- II. INCIDENT NARRATIVE
- III. MAP OF SITE
- IV. PHOTOGRAPHIC DOCUMENTATION
- V. DISPOSAL DOCUMENTATION





## **I. INCIDENT SUMMARY**

---

**RESPONSE DATE:** March 24, 2011

**TIME NOTIFIED:** 1440 Hours (CST)

**NOTIFIED BY:** Mike Mathey – Arrowcast Inc

**INCIDENT LOCATION:** Arrowcast Inc  
2900 East Richmond Street  
Shawano, Wisconsin 54166

**SITE CONTACT(S):** Mike Mathey – Arrowcast Inc

**INCIDENT TYPE:** Hydraulic Oil Release

**AMOUNT RELEASED:** Estimated 70 Gallons

**SOURCE:** Hydraulic Oil Filter on Sadoff Truck

**AFFECTED AREA(S):** Gravel, Snow Banks & Water Runoff

**WEATHER:** 35° Fahrenheit, Sunny

**WASTE GENERATED:** 28 – 55 Gallon Drums of Contaminated  
Gravel and Snow

4 – 55 Gallon Drums of Contaminated  
Pads and Boom

1000 Gallons of Hydraulic Oil and Water



## II. INCIDENT NARRATIVE

---

On March 24, 2011, at 1440 hours (CST), Veolia ES Special Services, Inc. (VES-SS) received a call from Mike Mathey with Arrowcast Inc. regarding a hydraulic oil release. The incident occurred at Arrowcast Inc located at 2900 East Richmond Street in Shawano, Wisconsin. An estimated 70 gallons of hydraulic oil had released onto the gravel and snow banks and was migrating into the water runoff. VES-SS was contracted to respond to the incident and perform the necessary clean up.

At 1645 hours (CST), VES-SS personnel arrived onsite to conduct a site assessment and map out the spill area. VES-SS found that the hydraulic oil had spilled from a blown off filter on a Sadoff Metal semi releasing approximately 70 gallons of hydraulic oil onto the gravel. The area had then been plowed, spreading the hydraulic oil into the snow banks and an area approximately 100 feet long by 40 feet wide in the gravel driveway. Due to the melting snow there was visible contamination in the runoff water and puddles in the driveway. Prior to VES-SS arrival, the Shawano Fire Department had placed absorbent pad and boom in the runoff water and Arrowcast Inc had dammed the runoff water from reaching the ditch areas. A brief safety meeting was conducted and a work plan formatted.

Utilizing a vacuum truck, VES-SS removed the sheen from the water runoff. The spent boom and pads were removed and placed into four 55 gallon metal drums. A skid steer provided by Arrowcast Inc was used to scrap the contaminated gravel and snow from the driveway and snow banks. The snow and gravel were contained in 21- 55 gallon drums. The drums were labeled and staged on Arrowcast Inc property until the snow melted and proper disposal could be arranged. One drum of hydraulic oil and snow from a release the night before from the same truck was added by Arrowcast and staged for disposal.

At 2135 hours, VES-SS personnel were offsite.

On March 25, 2011, VES-SS was contacted by Mr. Mathey requesting that VES-SS to return to site with 6 - 55 gallon drums to touch up a couple of areas in the driveway.





At 1100 hours (CST), VES-SS returned to site. Utilizing the Arrowcast Inc skid steer, additional areas from the snow banks and snow along the water runoff were removed and placed in the 6 - 55 gallon drums. The drums were labeled and placed with the others for holding. Absorbent pads were then placed in the water runoff path to collect any additional contamination in the water runoff. The pads were removed by Arrowcast Inc prior to freezing temperatures that night and placed into the 55 gallon drums onsite.

At 1300 hours (CST), VES-SS personnel were offsite.

On March 25, 2011, the 1000 gallons of hydraulic oil and water and the four drums of boom and pad were taken to Safety Kleen located in Kimberly, Wisconsin for recycling.

On April 5, 2011 the 28 - 55 gallon drums of hydraulic oil, water and gravel were removed from site. VES-SS field screened the affected gravel from site utilizing a photo ionization detector (PID) receiving results of 0.0 ppm for Volatile Organic Compounds (VOC's). The drums were then taken to the VES-SS Neenah, Wisconsin Facility for holding until approved for recycling by Safety Kleen.

On April 6, 2011, the drums were approved for recycling and delivered to Safety Kleen in Kimberly, Wisconsin. No further action was requested of VES-SS at this time.

VES-SS has been advised by the Wisconsin Department of Natural Resources (WDNR) to notify our clients that a copy of our Incident Response Report should be submitted to the WDNR for their records, and for closure of the incident site. We have not submitted a copy of this report to the WDNR, but have enclosed a copy for you to send if this report meets your approval. The copy of this report should be submitted to:

Wisconsin Department of Natural Resources  
Attn: Jason Moeller  
Northeast Region  
2984 Shawano Avenue  
Green Bay, Wisconsin 54307



All information presented in this report has been submitted with good intent and to the best of my knowledge.

REPORT COMPLETED BY: Greg Potts – Project Manager

A handwritten signature in black ink, appearing to read 'Greg Potts'.

DATE: April 6, 2011

REPORT REVIEWED BY: Chad Kraemer– Network Program Manager

A handwritten signature in black ink, appearing to read 'Chad Kraemer'.

DATE: April 6, 2011





### III. MAP OF SITE

---



VES-SS Project Number: 4901570.11.039

Response Date: 3-24-11



Arrowcast Inc

Spill Location



#### IV. PHOTOGRAPHIC DOCUMENTATION





Contaminated Area



Contaminated Area





Contaminated Area




Scraping of Snow and Gravel





Skimming of Oil on Runoff



Cleaned Area





Equipment Onsite



Staged Drums



Placing Snow and Gravel in Drums



Pads Placed on Runoff



## **V. DISPOSAL DOCUMENTATION**



Veolia ES Special Services, Inc.  
785 County Road CB, Suite 100  
Neenah, WI 54956  
Tel: 920-749-8100 - Fax: 920-749-8110  
www.VeoliaES.com

|   |  |  |  |                                      |  |  |  |   |  |  |  |
|---|--|--|--|--------------------------------------|--|--|--|---|--|--|--|
| <b>S</b><br>SAFETY-KLEEN  |  | 5360 Legacy Drive, Building 2, Suite 100<br>Plano, Texas 75024<br>CUSTOMER NO. |  | 800-669-5740<br>www.safety-kleen.com |  | <b>WE CARE</b>   |  | DUNS NO. 05-397-6551 FED. ID NO. 396080019  |  | <b>BRANCH TSD</b>  |  |
| FOR SERVICE CALL  |  | BRANCH-MANAGER   |  | DOC. EXP.                            |  | SCHEDULED SERVICE WEEK   |  | SCHEDULED TERRITORY   |  | REFERENCE NUMBER   |  |
| 920-731-3045  |  | 3236061  |  | VEDLIA                               |  | 785 County Road C1b Ste 100  |  | CREDIT CODE   |  | PREVIOUS BALANCE   |  |
| 3236061   |  | VEDLIA   |  | 785 County Road C1b Ste 100          |  | CREDIT CODE  |  | PREVIOUS BALANCE  |  | BAL OVER 60 DAYS   |  |
| CUSTOMER SEGMENT  |  | CHAIN  |  | OUTER COUNTRY                        |  | SVC. P/C   |  | PROD. P/C   |  | TAX EXEMPTION NUMBER   |  |
| LOCATION  |  | TAX EXEMPTION NUMBER   |  | C.O.M.S. TAX                         |  | PRODUCT TAX  |  | RELEASE NO.   |  | DATE   |  |
| SERVICE DATE  |  | SALES REP NO.  |  | CUSTOMER P.O. NUMBER                 |  | CUSTOMER PHONE #   |  | TAX CODE  |  | DATE EQPT/PROD ORDERED   |  |
| DEPT  |  | SERVICE/PRODUCT  |  | SURVEY NUMBER                        |  | UNIT PRICE   |  | QUANTITY  |  | CHARGE   |  |
| 1   |  | 55553  |  | 150129                               |  | 0.50   |  | 1000  |  | 0.50   |  |
| 2   |  | 122001   |  |                                      |  | 12.25  |  | 1   |  | 12.25  |  |
| 3   |  |  |  |                                      |  |  |  |   |  |  |  |
| 4   |  |  |  |                                      |  |  |  |   |  |  |  |
| 5   |  |  |  |                                      |  |  |  |   |  |  |  |
| 6   |  |  |  |                                      |  |  |  |   |  |  |  |
| 7   |  |  |  |                                      |  |  |  |   |  |  |  |
| 8   |  |  |  |                                      |  |  |  |   |  |  |  |
| 9   |  |  |  |                                      |  |  |  |   |  |  |  |
| TOTAL-SERVICE/PRODUCTS  |  | TANK CAPACITY  |  | TRANSPORTER                          |  | DATE   |  | 03/25/2011  |  | DATE   |  |
| GENERATOR STATUS: CHECK ONLY ONE BOX BELOW                                    |  | MANIFEST NO.   |  | USEPA TRANSPORTER ID NO.             |  | Kevin Moeller  |  | X   |  | DATE   |  |
| GENERATOR: HAZARDOUS WASTE CLASSIFICATION *                                   |  | VEHICLE FLUIDS ONLY  |  | OTHER NON-VEHICLE FLUIDS             |  | 12.25  |  | USEPA TRANSPORTER ID NO.  |  | DATE   |  |
| CESQG   |  | 1  |  | 3                                    |  | GENERATOR USEPA ID NO.   |  | GENERATOR STATE ID NO.  |  | DATE   |  |
| SQ/LQG  |  | 2  |  | 4                                    |  | John Covia   |  | X   |  | DATE   |  |
| 11 US DOT DESCRIPTION (INCLUDING PROPER SHIPPING NAME, HAZARD CLASS, AND ID.) |  | 12 CONTAINERS NO.  |  | 13. TOTAL QUANTITY                   |  | 14. UNIT WT/VOL  |  | SK DOT NUMBER   |  | DATE   |  |
| A. USED OIL AND WATER MIXTURE (NOT US DOT HAZARDOUS MATERIAL)                 |  | 17   |  | 1000                                 |  | Ba1927   |  | 0   |  | DATE   |  |
| B. PO# D06-102270   |  |  |  |                                      |  |  |  |   |  | DATE   |  |
| C.  |  |  |  |                                      |  |  |  |   |  | DATE   |  |
| D.  |  |  |  |                                      |  |  |  |   |  | DATE   |  |
| INTERMEDIATE FACILITY NAME AND ADDRESS  |  | USA EPA ID NO.   |  | STATE ID NO.                         |  | TOTAL DUE  |  | DO NOT WRITE IN THE AREA BELOW  |  | DATE   |  |
| CASH  |  | TOTAL RECEIVED   |  | APPLY PAYMENT TO:                    |  | CHARGE MY ACCOUNT FOR THIS TRANSACTION UNLESS OTHERWISE INDICATED IN THE PAYMENT RECEIVED SECTION. |  | Customer certifies that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the U.S. Environmental Protection Agency and the U.S. Department of Transportation. |  | ADDITIONAL TERMS AND CONDITIONS ON THE REVERSE SIDE OF THIS DOCUMENT ARE INCORPORATED HEREWITH MADE A PART HEREOF. |  |
| CHECK NUMBER  |  | INVOICE #  |  | AMOUNT \$                            |  | INVOICE #  |  | AMOUNT \$   |  | Print Name   |  |
| PREVIOUS CREDIT CARD NO.  |  | CREDIT CARD NO.  |  | AMEX VISA MC                         |  | EXP. DATE  |  | IN THE EVENT OF AN EMERGENCY CALL 1-800-468-1760 (24 hours)   |  | SEE REVERSE SIDE FOR IMPORTANT INFORMATION   |  |
| CUSTOMER REFERENCE INFORMATION  |  | MANIFEST CODE  |  | SEQ #                                |  | GENERATOR(S) / P/LR DESIGNATED REPRESENTATIVE SIGNATURE  |  | X   |  | DATE   |  |







Veolia ES Special Services, Inc.  
785 County Road CB, Suite 100  
Neenah, WI 54956  
Tel: 920-749-8100 - fax: 920-749-8110  
www.VeoliaES.com



5360 Legacy Drive, Building 2, Suite 100  
Plano, Texas 75024  
CUSTOMER NO.

800-666-5740

www.safety-keen.com



DUNS NO. 05-397-6551 FED. ID NO. 396090019

BRANCH TSD

GENERATOR  
CUSTOMER

VEOLIA ES INDUSTRIAL SERVICES

785 County Road C1b

Neenah WI 54956-7111 US

3236061

VEOLIA

785 County Road C1b Ste 100

Neenah WI US 54956-7111

SERVICE DATE SALES REP NO. CUSTOMER P.O. NUMBER CUSTOMER PHONE # TAX CODE DATE EQPT/PROD ORDERED SERVICE TAX C.O.M.S. TAX PRODUCT TAX

| DEPT | SERVICE/PRODUCT | SURVEY NUMBER | UNIT PRICE | QUANTITY | CHARGE | SALES TAX | TOTAL CHARGE | CHLORINE TEST RESULTS | SK DOT NUMBER | CC | SERVICE TERM | CHANGE SERVICE TERM (WEEKS/INITIALS) | CHANGE SK DOT DATE (YY-WW) | PROMO NO. | RELEASE NO. |
|------|-----------------|---------------|------------|----------|--------|-----------|--------------|-----------------------|---------------|----|--------------|--------------------------------------|----------------------------|-----------|-------------|
| 1    | 55553           | 150129        | 0.50       | 1        | 0.50   |           | 0.50         |                       | 24            |    |              |                                      |                            |           |             |
| 2    | 120001          |               | 12.25      | 1        | 12.25  |           | 12.25        |                       |               |    |              |                                      |                            |           |             |
| 3    |                 |               |            |          |        |           |              |                       |               |    |              |                                      |                            |           |             |
| 4    |                 |               |            |          |        |           |              |                       |               |    |              |                                      |                            |           |             |
| 5    |                 |               |            |          |        |           |              |                       |               |    |              |                                      |                            |           |             |
| 6    |                 |               |            |          |        |           |              |                       |               |    |              |                                      |                            |           |             |
| 7    |                 |               |            |          |        |           |              |                       |               |    |              |                                      |                            |           |             |
| 8    |                 |               |            |          |        |           |              |                       |               |    |              |                                      |                            |           |             |
| 9    |                 |               |            |          |        |           |              |                       |               |    |              |                                      |                            |           |             |

TOTAL-SERVICE/PRODUCTS

TANK CAPACITY

TRANSPORTER DATE 10/10/11

GENERATOR STATUS: CHECK ONLY ONE BOX BELOW  
GENERATOR: HAZARDOUS WASTE CLASSIFICATION \*  
VEHICLE FLUIDS ONLY  
OTHER NON-VEHICLE FLUIDS  
1 NO PREQUAL REQUIRED, NO HALOGEN TEST  
2 NO PREQUAL REQUIRED, HALOGEN TEST AT PICK-UP  
3 PREQUAL REQUIRED, NO HALOGEN TEST  
4 PREQUAL REQUIRED, HALOGEN TEST AT PICK-UP  
\* REFER TO REVERSE SIDE FOR DEFINITIONS

MANIFEST NO. 12.36

USEPA TRANSPORTER ID NO.

GENERATOR USEPA ID NO. GENERATOR STATE ID NO.

PRINT NAME SIGNATURE

FACILITY DATE 10/10/11

PRINT NAME SIGNATURE

11. US DOT DESCRIPTION (INCLUDING PROPER SHIPPING NAME, HAZARD CLASS, AND ID.)

12. CONTAINERS NO. TYPE 13. TOTAL QUANTITY 14. UNIT WT/VOL SK DOT NUMBER

A. USED OIL AND WATER MIXTURE (NOT USDOT HAZARDOUS MATERIAL)

B. 28 drums x \$75.00 = \$2100.00

C. PO# D06-102270

D. INTERMEDIATE FACILITY NAME AND ADDRESS

USA EPA ID NO.

STATE ID NO.

CASH CHECK NUMBER TOTAL RECEIVED

APPLY PAYMENT TO: TODAY'S SERVICE/SALE PREVIOUS BALANCE AS FOLLOWS

INVOICE # AMOUNT \$ INVOICE # AMOUNT \$

PREVIOUS CREDIT CARD NO. CREDIT CARD NO. AMEX VISA MC EXP. DATE

CUSTOMER REFERENCE INFORMATION

IN THE EVENT OF AN EMERGENCY CALL 1-800-458-1760 (24 hours)

CHARGE MY ACCOUNT FOR THIS TRANSACTION UNLESS OTHERWISE INDICATED IN THE PAYMENT RECEIVED SECTION.

Customer certifies that the above named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the U.S. Environmental Protection Agency and the U.S. Department of Transportation.

ADDITIONAL TERMS AND CONDITIONS ON THE REVERSE SIDE OF THIS DOCUMENT ARE INCORPORATED HERewith MADE A PART HEREOF.

Print Name

X GENERATOR/SHIPPER DESIGNATED REPRESENTATIVE SIGNATURE

SEE REVERSE SIDE FOR IMPORTANT INFORMATION

TOTAL DUE

DO NOT WRITE IN THE AREA BELOW

OIL RECOVERY SERVICE/ SALES ACKNOWLEDGMENT

PART NO. 1353 (07/10)





